
# DATA SHEET

## SKEW CLAMP

Skew clamp, with stainless steel separator, to connect rod to tape parallel or squarely. Clamp ensures good contact of rod and tape. In order to avoid stress corrosion of the clamp, use tape to isolate the clamp from the corrosive environment, i.e. the ground. Stress corrosion occurs in the case of synergy of two factors: the corrosive environment, i.e. the ground, and the constant stress force on the clamp plates caused by the twisted screws. Elimination of the corrosive environment prevents the occurrence of stress corrosion.

| Cat. no. | Dimensions | | Material |
|---|---|---|---|
| | rod St/Cu<br>mm | tape parallel or squarely to rod<br>mm | |
| C1030478N | 14.2; 16 | ≤ 40 | stainless steel 2 mm, stainless steel bolts M8 |
| C1030479N | 17.2 | ≤ 40 | |



The manufacturer reserves the right to change the product design without prior notice.

**CBM Technology Sp. z o.o.**
ul. Kasztanowa 2, 64-320 Niepruszewo, Poland
tel. +48/61 650 30 40
e-mail: office@cbm-technology.eu; www.cbm-technology.eu